

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT T	UNIT TYPE:													
Lined MSWLF	LCID	YW	Transfer	Compost	SLAS	X	COUNTY: Martin							
Closed MSWLF	HHW	White goods	Incin	T&P	FIRM		PERMIT NO.: SLAS-59-06							
CDLF	Tire T&P / Collection	Tire Monofill	Industrial Landfill	DEMO	SDTF		FILE TYPE: COMPLIANCE							

FACILITY NAME AND ADDRESS:

Brent Roberson Roberson Septic, LLC PO Box 1596 Williamston, NC 27892

GPS COORDINATES: <u>N</u>: 35.78754 <u>W</u>: -77.08752

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Brent Roberson*Telephone: 252-792-4155

Email address: brent@robersoncontracting.com

Fax: 252-792-9156

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: Chester Cobb

STATUS OF PERMIT: Active **EXPIRES:** 10/12/2015

PURPOSE OF SITE VISIT: Routine

STATUS OF PAST NOTED VIOLATIONS:

Upon review of the submitted septage land application logs, it was noted that the logs were missing time of discharge and pH of septage discharged. Failure to document time of discharge and pH is a violation of Rule .0838 e. 1. Records not checked on this inspection.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

- 1. Signage present at entrance to site.
- 2. The path to the site was in good shape.
- 3. Field markers present.
- 4. No septage discharges noticed outside of the permitted boundaries.
- 5. No spot dumps or thick applications observed.
- 6. Small grain overseed not up.
- 7. No application at time of inspection. pH not checked.
- 8. No objectionable odors noticed today.
- 9. No issues noted with any of the setbacks.
- 10. Records not checked.
- 11. Collected soil sample from the field.

Please contact me if you have any questions or concerns regarding this inspection report.

Chester R. Cobb

Regional Representative

Phone: (919) 707-8283

Sent on: 7/25/13	Email	Hand delivery	X	US Mail	Certified No. [_]